

101718, 344

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,798,700 B2
DATED : September 28, 2004
INVENTOR(S) : Jcung

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10.

Line 39, should read -- generating a control signal on a control line coupled to a --


Column 14.

Line 28, should read -- ground line is set to a first of the ground voltage or the --

Line 31, should read -- wherein the virtual ground line is set to a second of the --

Signed and Sealed this

Twenty-sixth Day of April, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office